



- #1: Galena-plateville, Under Maquoketa, Dry & Stable
- #2: Galena-Plateville, Des Plaines Disturbance
- #3: Galena-Plateville, No Maquoketa, Greater Than 75 Feet Below Bedrock Surface
- #4: Galena-Plateville, Sandwich Fault, Broken & Wet
- #5: Galena-Plateville, No Maquoketa, < 75 Below Bedrock Surface
- #6: Maquoketa, > 75 Below Bedrock Surface, Relatively Dry
- #7: Maquoketa, < 75 Below Bedrock Surface, Relatively Wet
- #8: Maquoketa, Des Plaines Disturbance
- #9: Silurian, > 75 Below Bedrock Surface, Relatively Dry
- #10: Silurian, < 75 Below Bedrock Surface, Relatively Wet
- #11: Silurian, Des Plaines Disturbance
- #12: St. Peter, Maquoketa Or Galena-Plateville Missing, Below Water Table
- #13: Prairie Du Chien, Sandwich Fault, Broken, Below Water Table
- #14: Prairie Du Chien, Below Water Table

- ▲ A Site
- ▲ B Site
- Mid Site
- ◆ Other EVN Site

- TBM A
UNSHIELDED TBM, LIMITED SUPPORT, LINING & GROUTING
- TBM B
OPEN TBM WITH FINGER SHIELD, ROCKBOLTS, MESH AND/OR RING BEAMS, WITH CAST IN PLACE CONCRETE LINER, WITH OR WITHOUT MEMBRANE, GROUTING
- TBM C
SEALED TBM WITH BOLTED & GASKETED CONCRETE LINER

